

MONTANA WELL LOG REPORT

Other Options

This well log reports the activities of a licensed Montana well driller, serves as the official record of work done within the borehole and casing, and describes the amount of water encountered. This report is compiled electronically from the contents of the Ground Water Information Center (GWIC) database for this site. Acquiring water rights is the well owner's responsibility and is NOT accomplished by the filing of this report.

[Return to menu](#)
[Plot this site in State Library Digital Atlas](#)
[Plot this site in Google Maps](#)

Site Name: MONTANA BUILD
GWIC Id: 302909

Section 1: Well Owner(s)
 1) SUTCH, BRYAN (MAIL)
 517 MOOSE CROSSING
 COLUMBIA FALLS MONTANA 59912 [06/13/2019]

Section 2: Location

Township	Range	Section	Quarter Sections
31N	20W	28	
County			Geocode

FLATHEAD

Latitude	Longitude	Geomethod	Datum
48.42147061575	-114.1651979265	TRS-SEC	NAD83
Ground Surface Altitude	Ground Surface Method	Datum	Date

Addition	Block	Lot
----------	-------	-----

Section 3: Proposed Use of Water
 DOMESTIC (1)

Section 4: Type of Work
 Drilling Method: ROTARY
 Status: NEW WELL

Section 5: Well Completion Date
 Date well completed: Thursday, June 13, 2019

Section 6: Well Construction Details

Borehole dimensions

From	To	Diameter
0	86	6

Casing

From	To	Diameter	Wall Thickness	Pressure Rating	Joint	Type
-2	86	6	0.25		WELDED	A53B STEEL

Completion (Perf/Screen)

From	To	Diameter	# of Openings	Size of Openings	Description
86	86	6			OPEN BOTTOM

Annular Space (Seal/Grout/Packer)

From	To	Description	Cont. Fed?
0	30	BENTONITE	

Section 7: Well Test Data

Total Depth: 86
 Static Water Level: 25
 Water Temperature:

Air Test *

20 gpm with drill stem set at 76 feet for 2 hours.
 Time of recovery _ hours.
 Recovery water level _ feet.
 Pumping water level _ feet.

** During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.*

Section 8: Remarks

Section 9: Well Log
Geologic Source

Unassigned

From	To	Description
0	16	FOREST FLOOR GRAVEL
16	26	SILTY SAND WATER
26	46	SILTY SAND WATER
46	66	CLAY GRAVEL
66	86	GRAVEL WATER

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name: CASEY OLSON
Company: RABCO SERVICES INC.
License No: WWC-646
Date Completed: 6/13/2019